

AMERICAN WIRE GAUGE CONVERSION CHART

AWG Number	Ø [Inch]	Ø [mm]	Ø [mm ²]	Resistance [Ohm/m]
4/0 = 0000	0.460	11.7	107	0.000161
3/0 = 000	0.410	10.4	85.0	0.000203
2/0 = 00	0.365	9.26	67.4	0.000256
1/0 = 0	0.325	8.25	53.5	0.000323
1	0.289	7.35	42.4	0.000407
2	0.258	6.54	33.6	0.000513
3	0.229	5.83	26.7	0.000647
4	0.204	5.19	21.1	0.000815
5	0.182	4.62	16.8	0.00103
6	0.162	4.11	13.3	0.00130
7	0.144	3.66	10.5	0.00163
8	0.128	3.26	8.36	0.00206
9	0.114	2.91	6.63	0.00260
10	0.102	2.59	5.26	0.00328
11	0.0907	2.30	4.17	0.00413
12	0.0808	2.05	3.31	0.00521
13	0.0720	1.83	2.62	0.00657
14	0.0641	1.63	2.08	0.00829
15	0.0571	1.45	1.65	0.0104
16	0.0508	1.29	1.31	0.0132
17	0.0453	1.15	1.04	0.0166
18	0.0403	1.02	0.823	0.0210
19	0.0359	0.912	0.653	0.0264
20	0.0320	0.812	0.518	0.0333
21	0.0285	0.723	0.410	0.0420
22	0.0253	0.644	0.326	0.0530
23	0.0226	0.573	0.258	0.0668
24	0.0201	0.511	0.205	0.0842
25	0.0179	0.455	0.162	0.106
26	0.0159	0.405	0.129	0.134
27	0.0142	0.361	0.102	0.169
28	0.0126	0.321	0.0810	0.213